

DRONETRACKER REPORT

CUSTOMER: DEDRONE DEVELOPERS

DATE: 06/20/2017 - 07/20/2017



398

TOTAL NUMBER OF INCIDENTS

Ø ALERTS / DAY	16.9
Ø INCIDENTS / DAY	13.3
Ø DURATION / INCIDENT	3 minutes
HOTSPOT ZONE	WARNING
MAX. INCIDENTS / DAY	73


TOP DRONES

NO.	Σ TIME	MODEL	FIRST SEEN	LAST SEEN	INCIDENTS
1	4 hours	DJI OcuSync	06/20/2017, 8:55:51 pm	07/18/2017, 9:59:20 pm	27
2	4 hours	DJI Lightbridge	06/21/2017, 5:04:00 pm	07/19/2017, 4:56:08 pm	59
3	3 hours	Hubsan Hubsan	06/22/2017, 9:50:42 am	07/20/2017, 3:37:06 pm	21
4	2 hours	DJI Lightbridge Retrofit	06/23/2017, 11:32:19 am	07/14/2017, 5:53:07 pm	31
5	an hour	DJI Phantom III Standard	07/03/2017, 9:48:57 am	07/20/2017, 1:14:43 pm	23
6	an hour	Parrot BEBOP 2	06/21/2017, 6:53:36 pm	07/17/2017, 4:44:38 pm	7
7	5 minutes	TTRobotix Wi-Fi	07/07/2017, 1:43:36 pm	07/07/2017, 2:00:06 pm	2
8	3 minutes	DJI Spark	07/20/2017, 1:02:57 pm	07/20/2017, 1:12:08 pm	4
9	a minute	Parrot AR Drone 2.0	06/27/2017, 9:26:09 am	07/05/2017, 8:32:10 am	5
10	a minute	Parrot Wi-Fi	06/21/2017, 9:45:05 am	07/16/2017, 8:22:34 pm	4
11	a few seconds	YUNEEC Wi-Fi	07/18/2017, 6:29:06 pm	07/18/2017, 9:38:09 pm	2
12	a few seconds	Graupner HoTT	07/19/2017, 1:06:07 pm	07/19/2017, 1:06:07 pm	1

This compilation shows the sum of durations of the same model or protocol-types in the reported period of time.

QUANTITY OF DRONES

Incidents per day



CRITICAL DRONE INCIDENTS

FIRST SEEN	DURATION	DRONE / REMOTE CONTROL	IDENTIFICATION
07/17/2017, 3:56:46 pm Zone: WARNING	an hour	Remote: Phantom II, FASST Manufacturer: DJI, Futaba Drone: BEBOP 2 Manufacturer: Parrot Protocol: Wi-Fi Drone or Remote: Unknown Manufacturer: DJI Protocol: Wi-Fi	ssid: Bebop2-013962 mac: a0:14:3d:c7:24:2e mac: 60:60:1f:02:60:1b
07/11/2017, 2:45:49 pm Zone: WARNING Zone: ALERT	33 minutes	Drone: Unknown Manufacturer: Hubsan Protocol: Hubsan Remote: Unknown Manufacturer: Hubsan Protocol: Hubsan	uuid: 0x9ede8c3d uuid: 0x9ede8c3d
07/14/2017, 9:34:35 am Zone: WARNING	23 minutes	Drone: Unknown Manufacturer: DJI Protocol: OcuSync Remote: Unknown Manufacturer: DJI Protocol: OcuSync	
07/17/2017, 11:01:52 am Zone: WARNING Zone: ALERT	20 minutes	Drone: Unknown Manufacturer: DJI Protocol: Lightbridge Remote: Unknown Manufacturer: DJI Protocol: Lightbridge	
07/19/2017, 10:45:00 am Zone: WARNING Zone: ALERT	20 minutes	Remote: Unknown Manufacturer: Hubsan Protocol: Hubsan Drone: Unknown Manufacturer: Hubsan Protocol: Hubsan	uuid: 0x9ede8c3d,0x9ede8e3d,0x9edf8c3d,0xbede8c3d uuid: 0x9ede8c3d
07/17/2017, 5:04:45 pm Zone: WARNING Zone: ALERT	19 minutes	Remote: Unknown Manufacturer: DJI Protocol: OcuSync Drone: Unknown Manufacturer: DJI Protocol: OcuSync	
07/17/2017, 4:46:09 pm Zone: WARNING Zone: ALERT	18 minutes	Drone: Unknown Manufacturer: DJI Protocol: OcuSync Remote: Unknown Manufacturer: DJI Protocol: OcuSync	
07/18/2017, 1:50:53 pm Zone: WARNING Zone: ALERT	18 minutes	Drone: Unknown Manufacturer: DJI Protocol: OcuSync Remote: Unknown Manufacturer: DJI Protocol: OcuSync	
07/14/2017, 10:02:36 am Zone: WARNING Zone: ALERT	17 minutes	Drone: Unknown Manufacturer: DJI Protocol: OcuSync Drone: Unknown Manufacturer: DJI Protocol: Lightbridge Retrofit Remote: Unknown Manufacturer: DJI Protocol: OcuSync	
07/19/2017, 4:21:44 pm Zone: WARNING Zone: ALERT	15 minutes	Remote: Unknown Manufacturer: Hubsan Protocol: Hubsan Drone: Unknown Manufacturer: Hubsan Protocol: Hubsan	uuid: 0x9ede8c3d uuid: 0x9ede8c3d

		Remote: Phantom II, FASST Manufacturer: DJI, Futaba	
07/19/2017, 1:52:58 pm Zone: WARNING Zone: ALERT	13 minutes	Remote: Unknown Manufacturer: Hubsan Protocol: Hubsan Drone: Unknown Manufacturer: Hubsan Protocol: Hubsan	uuid: 0x9ede8c3d uuid: 0x9ede8c3d
07/04/2017, 11:01:15 am Zone: WARNING Zone: ALERT	13 minutes	Drone or Remote: Unknown Manufacturer: DJI Protocol: Wi-Fi Drone: Phantom III Standard Manufacturer: DJI Protocol: Wi-Fi Remote: Phantom III Standard Manufacturer: DJI Protocol: Wi-Fi Drone: Phantom III Standard Manufacturer: DJI Protocol: Wi-Fi Drone: Phantom III Standard Manufacturer: DJI Protocol: Wi-Fi Drone or Remote: Unknown Manufacturer: DJI Protocol: Wi-Fi Remote: Phantom III Standard Manufacturer: DJI	mac: 60:60:1f:0e:a8:93 ssid: PHANTOM3_2268cf mac: 60:60:1f:0e:a8:93 ssid: PHANTOM3_2268cf mac: 60:60:1f:22:68:cf mac: 60:60:1f:22:68:cf mac: 60:60:1f:0e:a8:93 mac: 60:60:1f:0e:a8:93 mac: 60:60:1f:22:68:cf frequency: 5738000000
07/18/2017, 4:42:49 pm Zone: WARNING Zone: ALERT	13 minutes	Drone: Unknown Manufacturer: DJI Protocol: OcuSync Remote: Unknown Manufacturer: DJI Protocol: Lightbridge Remote: Unknown Manufacturer: DJI Protocol: OcuSync	
07/18/2017, 2:17:15 pm Zone: WARNING Zone: ALERT	12 minutes	Drone: Unknown Manufacturer: DJI Protocol: OcuSync Remote: Unknown Manufacturer: DJI Protocol: OcuSync	
06/21/2017, 5:08:45 pm Zone: WARNING	11 minutes	Drone: Unknown Manufacturer: DJI Protocol: Lightbridge Remote: Unknown Manufacturer: DJI Protocol: Lightbridge	frequency: 2406500000,2426500000,2466500000,2476500000 frequency: 2404000000
07/19/2017, 3:11:00 pm Zone: WARNING	11 minutes	Remote: Unknown Manufacturer: Hubsan Protocol: Hubsan Remote: Phantom II, FASST Manufacturer: DJI, Futaba	uuid: 0x9ede8c3d
06/23/2017, 11:32:19 am Zone: WARNING Zone: ALERT	9 minutes	Drone: Unknown Manufacturer: DJI Protocol: Lightbridge Drone: Unknown Manufacturer: DJI Protocol: Lightbridge Retrofit Remote: Unknown Manufacturer: DJI Protocol: Lightbridge	frequency: 2406500000 frequency: 2416500000 frequency: 2404000000
07/19/2017, 2:25:37 pm Zone: WARNING	9 minutes	Remote: Unknown Manufacturer: Hubsan Protocol: Hubsan	uuid: 0x9ede8c3d,0x9ede8c3f
07/18/2017, 1:32:36 pm Zone: WARNING Zone: ALERT	8 minutes	Drone: Unknown Manufacturer: Hubsan Protocol: Hubsan Remote: Unknown Manufacturer: Hubsan	uuid: 0x9ede8c3d uuid: 0x9ede8c3d

06/21/2017, 5:37:55 pm Zone: WARNING	8 minutes	Protocol: Hubsan Drone: Unknown Manufacturer: DJI Protocol: Lightbridge Remote: Unknown Manufacturer: DJI Protocol: Lightbridge	frequency: 2476500000 frequency: 2404000000
---	-----------	---	--

Drone incidents are critical, if the drone presence is over 5 minutes and it is located within a zone.

DIGIMET

NOTES

- Maximum period of time for a report is 31 days.
- Alerts under 15 seconds are ignored.
- An incident consists of at least one alert, which is minimum 15 seconds long. If an alert within the next minute with the same detection characteristic takes place, this is added to the same incident.

DIGINET